

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

874
NW
> 1
1.177 mi.
6212 ft.

**BAYSIDE FUEL OIL CORPORATION (1810 SHORE
1810 SHORE PARKWAY
BROOKLYN, NY 11214**

**NY LTANKS S103574068
NY VCP N/A
NY Spills**

**Relative:
Higher**

**Actual:
9 ft.**

LTANKS:

Name: BAYSIDE FUEL CORP
Address: 1810 SHORE PARKWAY
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9809992 / 2004-06-01
Facility ID: 9809992
Site ID: 250987
Spill Date: 1998-11-09
Spill Cause: Tank Failure
Spill Source: Non Major Facility > 1,100 gal
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1998-11-09
CID: 211
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1998-11-09
Spill Record Last Update: 2005-04-19
Spiller Name: SCOTT VITELLO
Spiller Company: BAYSIDE FUEL CORP
Spiller Address: 1810 SHORE PARKWAY
Spiller County: 001
Spiller Contact: SCOTT VITELLO

Spiller Phone: Not reported
Spiller Extension: Not reported
DEC Region: 2
DER Facility ID: 205715
DEC Memo: "This is a Voluntary Cleanup Agreement Site. File is located in inactive section. DEC (Sigona) conducted on-site inspection and sent letter to Bayside on 6/28/1999 concerning requirements for remediation. The site owner entered into a voluntary cleanup agreement under V00307-2. The results of the remedial action have been compiled into a final report by AKRF, dated July 15, 2003, certified by a NY PE on July 25, 2003. DEC Sigona sent the report to Mr. Geoffrey Laccetti, Public Health Specialist 3, NYS DOH, Flannigan Square, Troy, NY (518)402-7880 for comments and approval. DEC Sigona has determined based on DEC guidance that no further investigatory or remedial actions are warranted. However, DEC is awaiting comments from NYS DOH to provide a release for VCP. NYSDOH & DEC has certified the no further action and a release was issued."

Remarks: "CALLER DOING SOIL AND GROUNDWATER SAMPLING FOUND CONTAMINATION PBSNO: 2-603186"

All Materials:

Site ID: 250987
Operable Unit ID: 1070992

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Operable Unit: 01
Material ID: 313879
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 250987
Operable Unit ID: 1070992
Operable Unit: 01
Material ID: 313880
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

VCP:

Name: BAYSIDE FUEL OIL CORPORATION (1810 SHORE
Address: 1810 SHORE PARKWAY
City,State,Zip: BROOKLYN, NY 11214
Program Type: VCP
Site Code: 58381
HW Code: V00307
Site Class: C
SWIS: 2401

Region: 2
Town: New York City
Acres: Not reported
Date Record Added: 11/30/2000
Date Record Updated: 05/09/2007
Updated By: DXSMITH
Site Description:

The site is a former Petroleum Bulk Storage Facility, PBS no. 2-603180. At the time of the remedial action it served as a Maintenance facility for Bayside Fuel Corporation. The results of the remedial action are compiled in a final report dated July 15, 2003, certified by a NY PE on July 25, 2003. The remedial action has been completed, no further action/monitoring is required, and a release letter was issued on April 16, 2004. See also spill # 9809992.

Env Problem: A petroleum plume existed in the groundwater on the north side of the site. There was also localized contamination at several drywells. Contamination appeared to be a result of historical leaks, before the current owner purchased the property.

Health Problem: The site has been remediated, therefore, exposures to groundwater and soil are not expected. Remediation included excavation and removal of underground storage tanks, dry wells and contaminated soil. The site is also covered with buildings and pavement. Exposure to groundwater is unlikely since the area is served by public water supply.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Applicant/Requestor
Sub Type: ZZZ
Owner Name: Not reported
Owner Company: Alfred Allegretti/Bayside Fuel
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: ZZ
Owner Country: United States of America
HW Code: V00307
Waste Type: Petroleum Only
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: D2-1000-99-11(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: 9809992
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2007-04-27 10:36:00
Record Updated: 2007-04-27 10:36:00

Updated By: JAAVERSA

SPILLS:

Name: 1810 SHORE PKWY/BKLYN
Address: 1810 SHORE PARKWAY
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 8900205 / 1998-02-04
Facility ID: 8900205
Facility Type: ER
DER Facility ID: 205715
Site ID: 130003
DEC Region: 2
Spill Cause: Unknown
Spill Class: A1
SWIS: 2401
Spill Date: 1989-04-07
Investigator: SULLIVAN
Referred To: Not reported
Reported to Dept: 1989-04-07
CID: Not reported
Water Affected: Not reported
Spill Source: Tank Truck
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1989-04-10
Spill Record Last Update: 2004-04-27
Spiller Name: Not reported
Spiller Company: ANCHOR MOTOR
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: ""
Remarks: "SPILLAGE ON STREET & POSSIBLY IN SEWER, NYCFD ON SCENE."

All Materials:

Site ID: 130003
Operable Unit ID: 926499
Operable Unit: 01
Material ID: 451557
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 100.00
Units: G
Recovered: .00
Oxygenate: Not reported